

Inspection Photos

Location Name: CAERUS PICEANCE LLC Federal 29-6BB (PF-29) Pad

Location #: 334681



Photo # 3488 From entrance to location



Photo # 3489 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Federal 29-6BB (PF-29) Pad

Location #: 334681



Photo # 3490 Location



Photo # 3491 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Federal 29-6BB (PF-29) Pad

Location #: 334681



Photo # 3492 Location



Photo # 3493 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Federal 29-6BB (PF-29) Pad

Location #: 334681



Photo # 3494 Location



Photo # 3495 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Federal 29-6BB (PF-29) Pad

Location #: 334681



Photo # 3496 Hole in secondary containment liner



Photo # 3497 Hole patched by Caerus employee during inspection