

Inspection Photos

Loc: 309022

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 1/25/2024

County: LAS ANIMAS



Inspection Photos



Photo 1. This culvert has been cleaned out and maintained at Lat/Long:37.302109, -104.78223 .



Inspection Photos



Photo 2. It appears erosion was repaired by the Rampart 43-33 well site.



Inspection Photos



Photo 3. Facing southwest along. There has been repairs performed along the road and disturbed areas were seeded.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:309022 | Date: 1/25/2024

Inspection Photos



Photo 4. Facing southeast along the access road. It appears erosion has been repaired and snow was plowed off the road for access.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:309022 | Date: 1/25/2024

Inspection Photos



Photo 5. Facing toward the location.

