

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/26/2024

Submitted Date:

01/29/2024

Document Number:

707602310

**FIELD INSPECTION FORM**

Loc ID: 323336    Inspector Name: Evins, Bret    On-Site Inspection:     2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 76840  
Name of Operator: SCHNEIDER ENERGY SERVICES INC  
Address: P O BOX 889  
City: FORT MORGAN    State: CO    Zip: 80701

**Findings:**

10 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Bothwell, Kevin	(970) 867-9437	kbothwell@rivalservices.net	All Inspections
Schneider, Jeff	970-867-9437	jeff@schneiderenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
323336	LOCATION	AC			-	LION-65N64W 30SENW	AO

**General Comment:**

This is a BATTERY inspection.  
Well(s): 1: Producing | PR.  
Battery: Active.

Centralized Battery serves 1 Location ID (323336).  
(Well(s): 1: Producing | PR).

Centralized Battery serves 1 Tank Battery Facility ID (Pending).

Reference:  
A.) Field Inspection Report doc. #707602308 and/or Location ID #323336 for PR Well(s) info.  
B.) Field Inspection Report doc. #707602310 and/or Location ID #323336 for Battery / Facility, Equipment info.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Barbed wire.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Surrounded by earth berms.		
Corrective Action:		Date:	
<b>Equipment:</b>			
Type:	Horizontal Heated Separator	# 1	corrective date
Comment:			
Corrective Action:		Date:	
Type:	Gas Meter Run	# 1	
Comment:	Gas Sales. Calibration card(s) indicates calibration <= 1 year. Last calibration: 06/30/2023. Active.		
Corrective Action:		Date:	
Type:	Bird Protectors	# 1	
Comment:			

Corrective Action:	Date:
--------------------	-------

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment: <a href="#">Centralized Battery serves 1 Location ID (323336). (Well(s): 1: Producing   PR).</a> <a href="#">Centralized Battery serves 1 Tank Battery Facility ID (Pending).</a>					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.373390,-104.594930
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: <a href="#">Berms shared w/ crude oil tank(s), produced H2O tank(s).</a>					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	

Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: <a href="#">Berms shared w/ crude oil tank(s), produced H2O tank(s).</a>					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO				
Comment:					
Corrective Action:				Date:	

**Flaring:**

Type					
Comment:					
Corrective Action:				Date:	

**Inspected Facilities**

Facility ID: 323336 Type: LOCATION API Number: - Status: AC Insp. Status: AO

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p><a href="#">CECMC Inspection Report Summary:</a></p> <p>On FRI 01/26/2024 at approximately 13:04 hrs. I, Bret Evins, conducted an onsite inspection at:                      Operator Name: SCHNEIDER ENERGY SERVICES INC                      Location Name: LION-65N64W/30SEW                      Location ID: 323336                      Well Name(s):                      Lion #2.                      API:                      123-12877.                      Location County: Weld County, Colorado                      Weather: Partly Sunny, damp from prior storm.</p> <p>While there, I observed:                      Well(s): 1: Producing   PR.                      Battery: Active.</p> <p>Centralized Battery serves 1 Location ID (323336).                      (Well(s): 1: Producing   PR).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Routine inspection.</p>	evinsb	01/29/2024

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602311	Site photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6410712">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6410712</a>