

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal DOE 2-W-29 Pad

Location ID: 335255



Photo # 4220 From entrance to location



Photo # 4221 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal DOE 2-W-29 Pad

Location ID: 335255



Photo # 4222 Location



Photo # 4223 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal DOE 2-W-29 Pad

Location ID: 335255



Photo # 4224 Location



Photo # 4225 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal DOE 2-W-29 Pad

Location ID: 335255



Photo # 4226 Tank label weathered & some required info is illegible



Photo # 4227 Tank label weathered & some required info is illegible

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal DOE 2-W-29 Pad

Location ID: 335255



Photo # 4228 Line going from PA 321-29 well flowline to DOE 2-W-29 injection well

Photo # 4229 Line going from PA 321-29 well flowline to DOE 2-W-29 injection well

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal DOE 2-W-29 Pad

Location ID: 335255



Photo # 4230 Line going from PA 321-29 well flowline to DOE 2-W-29 injection well



Photo # 4231 Line going from PA 321-29 well flowline to DOE 2-W-29 injection well

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal DOE 2-W-29 Pad

Location ID: 335255



Photo # 4232 Line from PA 321-29 well flowline connected to line on DOE 2-W-29 injection well



Photo # 4233 Line from PA 321-29 well flowline connected to line on DOE 2-W-29 injection well

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal DOE 2-W-29 Pad

Location ID: 335255



Photo # 4234 Debris