

Caerus Piceance LLC  
Piceance creek Unit-62S97W 11NESW  
Loc ID: 335712



As signs are replaced additional information will be required

Entrance to location



Caerus Piceance LLC  
Piceance creek Unit-62S97W 11NESW  
Loc ID: 335712




Debris



Debris

Caerus Piceance LLC  
Piceance creek Unit-62S97W 11NESW  
Loc ID: 335712




**Rain cap missing**



**Unused equipment storage**



Caerus Piceance LLC  
Piceance creek Unit-62S97W 11NESW  
Loc ID: 335712



Rain cap missing



SENE or NESW?



Caerus Piceance LLC  
Piceance creek Unit-62S97W 11NESW  
Loc ID: 335712



Debris



Inaccurate well sign



Caerus Piceance LLC  
Piceance creek Unit-62S97W 11NESW  
Loc ID: 335712




Debris



As signs are replaced additional information will be required



Caerus Piceance LLC  
Piceance creek Unit-62S97W 11NESW  
Loc ID: 335712



Debris



Debris



**Caerus Piceance LLC**  
**Piceance creek Unit-62S97W 11NESW**  
**Loc ID: 335712**



**Location from Northeast entrance**



**Location from Northwest corner**



**Caerus Piceance LLC**  
**Piceance creek Unit-62S97W 11NESW**  
**Loc ID: 335712**



**Location from Southeast corner**



**Location from Southwest corner**