

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/03/2024

Submitted Date:

01/24/2024

Document Number:

698601479**FIELD INSPECTION FORM**Loc ID 304227 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 305 S RIDGE STREET #6279City: BRECKENRIDGE State: CO Zip: 80424**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:19 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
254226	WELL	PR	07/14/1998	GW	125-08104	NEWTON 12-5	PR

General Comment:Routine Inspection.

Location**Lease Road:**

Type	Access		
comment:	Two track off maintained County Road.		
Corrective Action:		Date:	

Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Content/Quantity/Hazard sign at tank.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Well sign located at production tank has no contact information on sign.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Well sign posted on gas meter run shed is missing Operator information.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Well sign located at well location. No contact information on sign,		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	No Emergency contact information posted at well location.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	02/24/2024

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Pump Jack drive belt guard noted on ground inside fencing.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Stock panel fencing around surface equipment at metering shed.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Stock panel fencing around surface equipment at well location.		
Corrective Action:		Date:	

Equipment:				corrective date	
Type: Gas Meter Run	# 1				
Comment:	Shared gathering location with the 125-11232. Digital Gas Meter Run. Meter Calibration/Test Log dated 12-6-23. Well Inlet Valve open. Gas Outlet Valve open.				
Corrective Action:				Date:	
Type: Vertical Separator	# 0				
Comment:					
Corrective Action:				Date:	
Type: Dehydrator	# 1				
Comment:	Dehydrator on supply gas line.				
Corrective Action:				Date:	
Type: Other	# 1				
Comment:	Shared Gas Meter Shed.				
Corrective Action:				Date:	
Type: Prime Mover	# 1				
Comment:	Gas fired motor. Drive belt currently off.				
Corrective Action:				Date:	
Type: Dehydrator	# 1				
Comment:	Dehydrator on gas meter run inlet.				
Corrective Action:				Date:	
Type: Pump Jack	# 1				
Comment:					
Corrective Action:				Date:	
Type: Bradenhead	# 1				
Comment:	Bradenhead plumbed to surface.				
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment:	Wellhead. Rods and tubing in the wellbore. Tubing valve open. Casing valve open.				
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	210 bbl
Other (Type)	

Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:

Flaring:					
Type					
Comment:					
Corrective Action:					Date:

--	--	--	--	--	--

Inspected Facilities									
Facility ID:	254226	Type:	WELL	API Number:	125-08104	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Rods and tubing in wellbore. Tubing valve open. Casing valve open. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open. Electronic Well File reflects last Production/Status reported 11/1/2023 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403665380	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6405242
698601550	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6405240