

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/26/2024

Submitted Date:

01/31/2024

Document Number:

707602322

FIELD INSPECTION FORM

Loc ID 302258 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 2001 16TH STREET SUITE 900
City: DENVER State: CO Zip: 80202

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297669	WELL	TA	08/01/2019	GW	123-28031	CONAGRA B 30-21	TA

General Comment:

This is a WELL inspection.
Well(s): 1: Temporarily Abandoned | TA.
Battery: Inactive | Shut-down.

Centralized Battery serves 3 Location IDs (302258, 302257, 336617).
(Well(s): 3: Temporarily Abandoned | TA ;1: Plugged & Abandoned | PA).

Centralized Battery Formerly served 2 Location IDs (302259, 323732).
(Well(s): 2: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID (Pending).

Reference (Associated Well(s), Battery Inspections):
A.) Field Inspection Report doc. #707602322 and/or Location ID #302258 for TA Well(s) info.
B.) Field Inspection Report doc. #707602324 and/or Location ID #302257 for TA Well(s) info.
C.) Field Inspection Report doc. #707602326 and/or Location ID #336617 for TA Well(s) info.
D.) Field Inspection Report doc. #707602328 and/or Location ID #302259 for PA Well(s) info.
E.) Field Inspection Report doc. #707602330 and/or Location ID #336617 for PA Well(s) info.
F.) Field Inspection Report doc. #707602332 and/or Location ID #302258 for Battery / Facility, Equipment info.

Location

Lease Road:

	Type Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:

	Type WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:

Equipment:

		corrective date
Type: Plunger Lift # 0		
Comment: Temporarily Abandoned TA. Equipment removed.		
Corrective Action:		Date:
Type: Other # 1		
Comment: Wellhead: w/ Master & casing valves.		
Corrective Action:		Date:
Type: Bradenhead # 1		
Comment: Appears plumbed to surface.		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.369793,-104.589691

Comment:	Centralized Battery serves 3 Location IDs (302258, 302257, 336617). (Well(s): 3: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (Pending).	
Corrective Action:		Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 297669 Type: WELL API Number: 123-28031 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Temporarily Abandoned | TA.
Disconnected from flowline.
Locked-Out, Tagged-Out | LOTO.
OOSLAT applied at flowline valve.
Blue TA tag posted.
CECMC records last production: 08/2017.

Form 4 on file. TA date: 04/10/2019. Approved.
DH-CIBP set.
Form 21 MIT on file. MIT date: 07/03/2019. Approved.
Form 6A on file. Out-of-Svc Designation.
Date: 08/16/2017. Approved.

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 08/27/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On FRI 01/26/2024 at approximately 15:43 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: CONAGRA B-65N64W/30NWSE Location ID: 302258 Well Name(s): Conagra B 30-21. API: 123-28031. Location County: Weld County, Colorado Weather: Partly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Routine inspection.</p>	evinsb	01/31/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602323	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6414479