





© 26-Jan-24 08:04:47 AM
ECMC Environmental Inspection Jillson





WGS84
±118ft

40.11689, -104.99134

ft
±11ft

4978

±10

NW341



© 26-Jan-24 08:05:41 AM
ECMC Environmental Inspection Jillson









© 26-Jan-24 08:06:30 AM
ECMC Environmental Inspection Jillson





© 26-Jan-24 08:06:47 AM
ECMC Environmental Inspection Jillson





WGS84
±16ft

40.11530, -104.99106

ft
±11ft

49.78

°T
±17

SE153



© 26-Jan-24 08:23:42 AM
ECMC Environmental Inspection Jillson



WGS84
±16ft

40.11527, -104.99109

±11ft

4976



±17

NE15



© 26-Jan-24 08:23:51 AM
ECMC Environmental Inspection Jillson







WGS84 40.11532, -104.99079 4976 W275



© 26-Jan-24 08:24:46 AM
ECMC Environmental Inspection Jillson



© 26-Jan-24 08:25:03 AM
ECMC Environmental Inspection Jillson



WGS84
±16ft
40.11533, -104.99088
ft
±11ft
4976
°T
±19
NW294

© 26-Jan-24 08:25:05 AM
ECMC Environmental Inspection Jillson













WGS84 40.11543 -104.99093 M ft 4979 NE70
#16ft ±11ft ±17



© 26-Jan-24 08:26:03 AM
ECMC Environmental Inspection Jillson





Improper stormwater BMP installation
© 26-Jan-24 08:26:24 AM
ECMC Environmental Inspection Jillson