

Inspection Photos

Loc: 321179

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 1/30/2024

County: BACA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Northeast corner of the location facing west. The fill slope has not been regraded and perennial vegetation has not established. This area westward consists mostly of undesirable weeds.



Inspection Photos



Photo 2. Facing at the north center side of the location. This area approximately 40'x40' has minimal vegetation growth.



Inspection Photos



Photo 3. Northwest corner of the location facing east. The fill slope has not been regraded and perennial vegetation has not established. This area eastward consists mostly of undesirable weeds.



Inspection Photos



Photo 4. Southwest side of the location facing west. The southern portion of the location has a good stand perennial vegetation.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321179 | Date: 1/30/2024

Inspection Photos



Photo 5. The southern center of the location has this area of sparse vegetation with some gravel that remains..

