

Inspection Photos

Loc: 321186

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 1/30/2024

County: BACA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west at the beginning of the access road. Vegetation has not reestablished in this area.



Inspection Photos



Photo 2. Facing west along the access road. Vegetation has established along this portion of the road.



Inspection Photos



Photo 3. There is a perimeter fence that remains in disrepair around the location.



Inspection Photos



Photo 4. Facing southwest toward the location cut slope. The cut slope needs to be recontoured with fill slope material to match pre-existing grade.



Inspection Photos



Photo 5. Facing east toward the location cut slope. The cut slope needs to be recontoured with fill slope material to match pre-existing grade..



Inspection Photos



Photo 6. Northwest corner of the location facing east. The ill slope has not been recontoured to match the surrounding grade. The perennial vegetation has not established along the fill slope area.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:321186 | Date: 1/30/2024

Inspection Photos



Photo 7. Facing east along the fill slope which is approximately 10 ft from the existing grade. The perennial vegetation has not established along the fill slope area.

