

# 01/30/24 INSPECTION PHOTOS

## SOMCOE, LLC TIFFANY 5 LOCATION





01.30.2024

PA well 06629, backfilled but not  
contoured













01.30.2024









01.30.2024









01.30.2024





01.30.2024





01.30.2024













01.30.2024





**SIMCOE LLC**  
TIFFANY 5-2  
ELEVATION: 6637 API #: 05-067-10028-00 ID #: 312083  
NAME OF TRIBE: N/A LEASE TYPE: N/A  
LEASE #: M00CH201510 CA #: C0C060317X  
SURFACE LOCATION: SWSE SEC 20 - T33N - R6W 893' FSL 16'  
BOTTOM HOLE LOCATION: NENE SEC 20 - T33N - R6W 338' FSL 16'  
LATITUDE: 37.084597 LONGITUDE: -107.520519  
SIMCOE LLC CONTROL CENTER 24 HR. PHONE #: 970-247-6916  
EMERGENCY CONTACT #: 911

**SIMCOE LLC**  
TIFFANY 5-3  
ELEVATION: 6637 API #: 05-067-10027-00 ID #: 312083  
NAME OF TRIBE: N/A LEASE TYPE: N/A  
LEASE #: M00CH201510 CA #: C0C060317X  
SURFACE LOCATION: SWSE SEC 20 - T33N - R6W 810' FSL 1567' FEL  
BOTTOM HOLE LOCATION: NWSW SEC 29 - T33N - R6W 228' FSL 1497' FEL  
LATITUDE: 37.084393 LONGITUDE: -107.520142  
SIMCOE LLC CONTROL CENTER 24 HR. PHONE #: 970-247-6916  
EMERGENCY CONTACT #: 911

01.30.2024





01.30.2024





01.30.2024





01.30.2024

Stormwater erosion south edge  
middle





Stormwater breach of location berm









Stormwater run off going  
through/under wattles





01.30.2024

Stormwater BMPs in disrepair due to  
livestock or wildlife





Stormwater erosion channel south  
end of location









01.30.2024





01.30.2024





01.30.2024






“0” flammability on NFPA , no  
capacity

01.30.2024





"0" flammability NFPA, no capacity





Standing water in containment,  
appears clean





01.30.2024

Discolored water in compressor skid  
should be treated as waste













01.30.2024














01.30.2024





No visible meter calibration record





01.30.2024





Open mousehole









Small trash

01.30.2024





01.30.2024

Debris





Muffler engine oil stain