

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/29/2024

Submitted Date:

01/30/2024

Document Number:

707800687

FIELD INSPECTION FORM

 Loc ID: 335249
 Inspector Name: Ramsey, Scott
 On-Site Inspection:
 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 14 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Operator Information:
 OGCC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202
Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211130	WELL	PR	10/10/1994	GW	045-06889	BENZEL 26-16 (P26NW)	PR
257512	WELL	PR	06/01/2003	GW	045-07566	BENZEL 25-13 (P26NW)	PR
257513	WELL	PR	06/01/2002	GW	045-07567	BENZEL 25-12 (P26NW)	PR
257514	WELL	PR	03/24/2004	GW	045-07568	BENZEL 26-9 (P26NW)	PR
257515	WELL	PR	06/01/2002	GW	045-07569	BENZEL 36-4 (P26NW)	PR

General Comment:**ECMC Inspection Report Summary**

On Monday 1/29/2024, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus P26NW, at Location # 335249 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Access road and location are lacking stabilization, some light tracking was observed from location to access road. Entrance from county road 319 onto access road to locations has approximately 20 feet of gravel for tracking control onto county road, but needs maintained.
2. Fencing laying around well heads is unused equipment, talked with pumper and was told some fencing was stolen. He was going to talk to his boss and see if they wanted to put the fencing back up or just remove it. He said it would be taken care of by end of day. Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Fencing laying around well heads is unused equipment, talked with pumper and was told some fencing was stolen. He was going to talk to his boss and see if they wanted to put the fencing back up or just remove it. He said it would be taken care of by end of day. There fore no C/A is issued. Inspector will check if completed on follow up for stormwater C/A		
Corrective Action:			Date:

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type				corrective date
Type: Gas Meter Run	# 6			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 5			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 5			

Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 5		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
--------	----	--	--

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	<u>211130</u>	Type:	<u>WELL</u>	API Number:	<u>045-06889</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>257512</u>	Type:	<u>WELL</u>	API Number:	<u>045-07566</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>257513</u>	Type:	<u>WELL</u>	API Number:	<u>045-07567</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>257514</u>	Type:	<u>WELL</u>	API Number:	<u>045-07568</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>257515</u>	Type:	<u>WELL</u>	API Number:	<u>045-07569</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing</u>								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Gravel				Sparse to none in some areas
		Compaction				Light compaction in areas
Compaction						Light compaction in areas
Gravel						Sparse to none in some areas

Comment: 1. Access road and location are lacking stabilization, some light tracking was observed from location to access road. Entrance from county road 319 onto access road to locations has approximately 20 feet of gravel for tracking control onto county road, but needs maintained.

Corrective Action: Maintenance relative to storm water runoff, operators shall consider seasonal factors, such as winter snow cover and spring runoff from snowmelt, to ensure site conditions and controls are adequate and in place to effectively manage storm water. Instal or maintain BMP's

Date: 03/12/2024

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707800695	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6416250