

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/25/2024

Submitted Date:

01/26/2024

Document Number:

694500615

FIELD INSPECTION FORMLoc ID 324639 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Afton liams		aliiams@foundationenergy.com	
Smith, James	972-707-2595	jsmith@foundationenergy.com	
Kelly Elliot		kaelliott@blm.gov	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212231	WELL	PA	05/19/2021	OW	057-06124	ALLARD 30-8-5	EI

General Comment:

ON 1/25/24 ECMC staff, Kris Neidel inspected location 324639, Allard 30-8-5. The location is part of REM Project # 17342. At the time of inspection, the location was under snow cover and drifted snow. weather was overcast and 22 degrees. The well has been plugged, no process equipment is on the location or at the site of the former wellhead. There is a pile of stockpiled soil that was reported in REM project 17342, the pile has; a plastic fence, straw waddles and an electric wire running the perimeter. The electric wire and fencing is fallen down in the snow. Corrective Actions: Per 913.b.(5)Ensure that livestock can not access or surface water to contact the stockpiled soil. See attached photos.

Inspected Facilities									
Facility ID:	212231	Type:	WELL	API Number:	057-06124	Status:	PA	Insp. Status:	EI

--

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Piles	Inadequate		
Comment	There is a pile of stockpiled soil that was reported in REM project 17342, the pile has; a plastic fence, straw waddles and an electric wire running the perimeter.			
Corrective Action	Per 913.b.(5)Ensure that livestock can not access or surface water to contact the stockpiled soil.			Date: 02/02/2024

Spill/Remediation:

Comment:

Corrective Action:

Date:

Emission Control Burner (ECB):

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403668096	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6408543
694500616	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6408526