

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/25/2024

Submitted Date:

01/26/2024

Document Number:

708902893**FIELD INSPECTION FORM**Loc ID 335828 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:26 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276270	WELL	PR	12/08/2005	GW	045-10429	N.PARACHUTE EF15D C27 595	PR
276271	WELL	PR	12/07/2005	GW	045-10430	N.PARACHUTE EF14D C27 595	PR
276272	WELL	PR	12/08/2005	GW	045-10431	N.PARACHUTE EF03D C27 595	PR
276273	WELL	PR	12/06/2005	GW	045-10432	N. Parachute EF05D C27 595	PR

General Comment:**CECMC Inspection Report Summary**

On 01/25/2024 at approximately 12:31 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up inspection at CAERUS PICEANCE LLC N.PARACHUTE EF15D C27 595 Pad.

Location # 335828 in Garfield County Colorado.

Please refer to inspection 708902651 conducted on 12/28/2023, previous corrective action has not been completed.

Location is within High Priority/Density/NSO/Black Bear Habitat areas.

Location is approximately 61 yards from East Fork Parachute Creek.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Signs/Marker - Signage on all wellheads insufficient/signs are not in compliance with CECMC rules with a CA date of 01/29/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Type	BATTERY		
Comment:	No tank battery on location		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Signage on all wellheads insufficient/signs are not in compliance with CECMC rules		
Corrective Action:	Comply with CECMC signage rules		Date: 01/29/2024
Emergency Contact Number:			
Comment:	911/970-285-2615		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	1 Chemical tank - Jersey barriers		
Corrective Action:			Date:

Type	WELLHEAD		
Comment:	Jersey barriers & pipe rail fence		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sales/gas lift meter houses & test meter - pipe rail fence		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Thermoelectric generator		
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:	Sales		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	Separator/test meter unit		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas lift		
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	276270	Type:	WELL	API Number:	045-10429	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger & gas lift								
Corrective Action:						Date:			
Facility ID:	276271	Type:	WELL	API Number:	045-10430	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger & gas lift								
Corrective Action:						Date:			
Facility ID:	276272	Type:	WELL	API Number:	045-10431	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger & gas lift								
Corrective Action:						Date:			
Facility ID:	276273	Type:	WELL	API Number:	045-10432	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger & gas lift								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Culverts				
				Material Handling And Spill Prevention		Chemical tank containments
		Compaction				Light compaction in some sections
Compaction						
		Gravel				Sparse to none

Comment: [Limited Stormwater inspection due to snow.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Please refer to Signs/Marker for observed compliance issues.	smelserw	01/26/2024
Production separation equipment & production tanks located at Middlefork Station facility #s 419757 & 470699		

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403668463	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6408955
708902894	Inspection 708902893 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6408950
708902895	Inspection 708902893 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6408951