

Final Reclamation and Stormwater Inspection

Date: 1/26/24

Operator: Vista Operating Inc - 100128

Location ID: 317407

Inspection Document #: 713900321

Washington County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: Scottie-Hickert 42-33

Location ID: 317407



Photo 1. The photo was taken at the well location facing North. The photo illustrates a large area of bare soil where the well was located, though a large portion of the well location has good vegetative cover.

Photo 2. The photo was taken at the well location facing East. The photo illustrates good vegetative cover on the eastern portion of the well location.

Inspection Photos

Location Name: Scottie-Hickert 42-33

Location ID: 317407



Photo 3. The photo was taken at the well location facing South. The photo illustrates good vegetative cover on the southern portion of the well location.



Photo 4. The photo was taken at the well location facing West. The photo illustrates good vegetative cover on the western portion of the well location.

Inspection Photos

Location Name: Scottie-Hickert 42-33

Location ID: 317407



Photo 5. The photo was taken at the well location facing North. The photo illustrates a point along the access road that is not vegetated that demonstrates several areas on the access road do not meet reclamation standards.

Photo 6. The reference photo was taken near the well location facing North.

Inspection Photos

Location Name: Scottie-Hickert 42-33

Location ID: 317407



Photo 7. The photo is USGS imagery from 09/02/1980. The photo illustrates there were no access roads prior to O&G activities where Well API #121-10874 and #121-10873 were spud.

Photo 8. The photo is from Google Earth imagery from September of 2023 and illustrates the access roads still visible between the two wells.