

Inspection Photos

Loc: 321180

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 1/30/2024

County: BACA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east toward the access road. This area of the road remains swaled and was not recontoured.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321180 | Date: 1/30/2024

Inspection Photos



Photo 2. Facing east toward the location. The well pad was never recontoured.



Inspection Photos



Photo 3. West side of the location consists mostly of undesirable weeds (Russian thistle).



Inspection Photos



Photo 4. Northwest corner of the location facing east.



Inspection Photos



Photo 5. Facing northeast at the north side of the location. The soil appears to be impacted and vegetation is not establishing.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321180 | Date: 1/30/2024

Inspection Photos




Photo 6. Facing northwest at the north side of the location. The soil appears to be impacted and erosion is occurring along this area.



Inspection Photos



Photo 7. Facing southwest along the cut slope.



Inspection Photos



Photo 8. South side of the location facing north.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321180 | Date: 1/30/2024