

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Good Housekeeping:

Type	DEBRIS		
Comment:	Weeds at Wellhead; see photos		
Corrective Action:	Comply with Rule 606	Date:	02/16/2024
Type	UNUSED EQUIPMENT		
Comment:	2" Riser at Wellhead not marked; see photos		
Corrective Action:	Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.	Date:	02/16/2024

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

Equipment:

Type: Other	# 1		corrective date
Comment:	TA Wellhead		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
------	--	--	--

Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 298435 Type: WELL API Number: 123-29065 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: TA - 06.01.2020. Form 6A 403118488 dated 08.16.2022 with a Plug Due Date of 12.31.2030

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
Routine Field Inspection. Weeds at Wellhead and Unmarked Riser at Wellhead	petrie	02/02/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696305901	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6417590