

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/30/2024

Submitted Date:

02/02/2024

Document Number:

708902951**FIELD INSPECTION FORM**Loc ID 415673 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:23 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	
Toews, Wesley		wtoews@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
415696	WELL	SI	08/01/2022	GW	045-19138	SGV FEDERAL 7-41A (8D)	SI

General Comment:**CECMC Inspection Report Summary**

On 01/30/2023 at approximately 09:35 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection at CAERUS PICEANCE LLC SGV FEDERAL 8D Pad.

Location # 415673 in Garfield County Colorado.

Location is within High Priority/Black Bear/NSO Habitat areas.

Location is approximately 86 yards from Pete & Bill creek.

While there, I observed plug & abandon operations on the SGV FEDERAL 7-41A well API # 045 - 19138.

Please refer to document #'s 403666399 & 403666377

Limited inspection due to ongoing plug & abandon operations on location.

This is a summary of inspection report.

Any corrective actions from previous inspections that have not been addressed are still applicable.

Dual lease, shared facilities with FEDERAL SOUTH PARACHUTE 22-8, location # 324344

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	Rig sign at the first point of intersection of public road and rig access road. Rig signs at most access road intersections, however 1 intersection along the lease road was not marked with rig sign. Spoke with Caerus consultant about the issue & also spoke to Romana Cowden with Caerus by phone about the issue. No CA issued at this time, however if this issue persists CA's will be issued in the future. Will follow up on the compliance issue in an email.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 2		
Comment:	500 bbl frac tanks		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Light plant		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Cement pump truck		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	110 bbl roll top tank		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Accumulator		

Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Rig heater		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Workover rig		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Wireline truck		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Cat telehandler		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Rig pump		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Rig tank		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Cement truck		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	415696	Type:	WELL	API Number:	045-19138	Status:	SI	Insp. Status:	SI
Cement									
Cement Contractor									
Contractor Name: SWABBCO					Contractor Phone:				
Surface Casing									
Cement Volume (sx):					Circulate to Surface:				
Cement Fall Back:					Top Job, 1" Volume:				
Intermediate Casing									
Cement Volume (sxs):					Good Return During Job:				
Production Casing									
Cement Volume (sx):					Good Return During Job:				
Plugging Operations									
Depth Plugs(feet range):					Cement Volume (sx):				
Good Return During Job:					Cement Type:				
Comment: Observed workover rig getting ready to fish tubing. 1 lease road intersection missing rig signage.									
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				Sparse to none in sections
		Ditches				
		Compaction				Large amount of light compaction in some sections
		Culverts				
Gravel						Sparse to none
Compaction	Fail					Lack of stabilization/compaction

Comment: 1. Lack of stabilization/compaction in areas on location.

Previously advised by supervisor Shawn Kellerby not to issue Stormwater corrective actions at this time due to spring creek area fire.

Limited Stormwater inspection due to snow.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Limited inspection due to ongoing plug & abandon operations on location.	smelserw	02/02/2024
Please refer to Signs/Marker & Inspected Facilities for comments.		
Any corrective actions from previous inspections that have not been addressed are still applicable.		
Dual lease, shared facilities with FEDERAL SOUTH PARACHUTE 22-8, location # 324344		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708902952	Inspection 708902951 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6417808
708902953	Inspection 708902951 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6417809