

# Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 35L-795 Pad

Location ID: 416986



Photo # 5248 From entrance to location



Photo # 5249 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 35L-795 Pad

Location ID: 416986



Photo # 5250 Location



Photo # 5251 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 35L-795 Pad

Location ID: 416986



Photo # 5252 Location



Photo # 5253 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 35L-795 Pad

Location ID: 416986



Photo # 5254 Location




Photo # 5255 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 35L-795 Pad

Location ID: 416986



Dec 7, 2023 at 1:01:25 PM  
CO



Feb 1, 2024 at 1:21:37 PM  
CO

**Photo # 8840 From inspection 708902470 conducted on 12/07/2023 Unused equipment**

**Photo # 5256 Unused equipment**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 35L-795 Pad

Location ID: 416986



Photo # 5257 Rupture disc vent line lacks cap




Photo # 5258 Rupture disc vent line lacks cap

## Inspection Photos

Location Name: CAERUS PICEANCE LLC BATTLEMENT MESA 35L-795 Pad

Location ID: 416986



**Photo # 5259 Open ended piping/wildlife hazards/available for entry by wildlife**