

Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 36L-795 Pad

Location ID: 334180



Photo # 5203 From entrance to location



Photo # 5204 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 36L-795 Pad

Location ID: 334180



Photo # 5205 Location



Photo # 5206 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 36L-795 Pad

Location ID: 334180




Photo # 5207 Location



Photo # 5208 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 36L-795 Pad

Location ID: 334180



Photo # 5209 Location




Photo # 5210 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 36L-795 Pad

Location ID: 334180



Photo # 8782 From inspection 708902455 conducted on 12/07/2023 Wellhead lacks required signage




Photo # 5211 Wellhead lacks required signage

Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 36L-795 Pad

Location ID: 334180



Photo # 5212 Wellhead lacks required signage



Photo # 5213 Open ended load line

Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 36L-795 Pad

Location ID: 334180



Photo # 8783 From inspection 708902455 conducted on 12/07/2023 PRV & rupture disc vent lines terminate in an unsafe manner



Photo # 5214 PRV & rupture disc vent lines terminate in an unsafe manner

Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 36L-795 Pad

Location ID: 334180



Photo # 8784 From inspection 708902455 conducted on 12/07/2023 PRV & rupture disc vent lines terminate in an unsafe manner



Photo # 5215 PRV & rupture disc vent lines terminate in an unsafe manner

Inspection Photos

Location Name: CAERUS PICEANCE LLC Battlement Mesa 36L-795 Pad

Location ID: 334180

Feb 1, 2024 at 1:02:30 PM



Photo # 5216 Debris