

Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE 20-8 (PI20) Pad

Location #: 335039



Photo # 5693 From entrance to location



Photo # 5694 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE 20-8 (PI20) Pad

Location #: 335039



Feb 5, 2024 at 1:45:21 PM
CO

Photo # 5695 Location



Feb 5, 2024 at 1:46:36 PM
CO

Photo # 5696 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE 20-8 (PI20) Pad

Location #: 335039



Photo # 5697 Location



Photo # 5698 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE 20-8 (PI20) Pad

Location #: 335039



Photo # 5699 Flowline heating insulation open ended/wildlife hazard/available for entry by wildlife



Photo # 5700 Hole in flowline heating insulation/wildlife hazard/available for entry by wildlife

Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE 20-8 (PI20) Pad

Location #: 335039



Photo # 5701 Flowline heating insulation open ended/wildlife hazard/available for entry by wildlife



Photo # 5702 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE 20-8 (PI20) Pad

Location #: 335039



Photo # 5703 Debris



Photo # 5704 Improperly marked deadman