

Inspection Photos Location: Tanner "E" 1 Facility ID: 321098 API #: 05-009-06450

COGIS - Related Facilities

Facility Type	Facility ID	Facility Name	Operator Name	Status	Field Name	Location	Location ID
WELL	05-009-06450	TANNER REC UNIT (E) 1	INVESTMENT EQUIPMENT LLC	11/11/2019	WELL	NE 1/4 10S40N	321098

Related Results

For local information, click on facility type.

Facility Type	Facility ID	Facility Name	Search Results	Status	Field Name	Location	Location ID	map
WELL	114627	TANNER "E" 1	001 UEL INC	01	01/01/19	WELL	NE 1/4 10S40N	321098
LOCATION	321098	TANNER REC UNIT (E) 1	INVESTMENT EQUIPMENT LLC	01	01/01/19	WELL	NE 1/4 10S40N	321098
WELL	05-009-06450	TANNER REC UNIT (E) 1	INVESTMENT EQUIPMENT LLC	01	01/01/19	WELL	NE 1/4 10S40N	321098
DEFICATION ONLINE	477212	Production Unit	INVESTMENT EQUIPMENT LLC	01	01/01/19	WELL	NE 1/4 10S40N	321098
DEFICATION ONLINE	477212	Production Unit	INVESTMENT EQUIPMENT LLC	01	01/01/19	WELL	NE 1/4 10S40N	321098

Related Samples

Search Results: No records found



Photo 1 –Location Information

Photo 2 – Location Overview

Inspection Photos
Location: Tanner "E" 1
Facility ID: 321098
API #: 05-009-06450



Photo 3 – Spoil Pile on south end of location

Photo 4 – Unused Equipment

Inspection Photos
Location: Tanner "E" 1
Facility ID: 321098
API #: 05-009-06450



Photo 5 – Spoil Pile on south end of location

Photo 6 – Spoil Pile on location

Inspection Photos
Location: Tanner "E" 1
Facility ID: 321098
API #: 05-009-06450



Photo 7 – Spoil Pile



Photo 8 – Historical Impacts observed beyond fence line on north side of location

Inspection Photos
Location: Tanner "E" 1
Facility ID: 321098
API #: 05-009-06450



Photo 9 – Inside Building, Impacted soils observed

Photo 10 – Inside Building, Impacted soils observed



Inspection Photos
Location: Tanner "E" 1
Facility ID: 321098
API #: 05-009-06450



Photo 11 – Equipment in Skid Building



Photo 12 – Historical Building/Unused Equipment

Inspection Photos
Location: Tanner "E" 1
Facility ID: 321098
API #: 05-009-06450



Photo 13 – Impacted soils on the North end of location

Photo 14 – Spoil Pile with impacted soils



Inspection Photos
Location: Tanner "E" 1
Facility ID: 321098
API #: 05-009-06450



Photo 15 – Spoil Pile with impacted soils



**Photo 16 – Impacted material next to mound of soil,
During the time of inspection on 1/30/2024 it was
noted the impacted material was no longer present**

