

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/31/2024

Submitted Date:

01/31/2024

Document Number:

702502329**FIELD INSPECTION FORM**Loc ID 316308 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num:                     **Operator Information:**OGCC Operator Number: 10775Name of Operator: KT RESOURCES LLCAddress: 3381 WESTBROOK LANECity: HIGHLANDS State: CO Zip: 80129**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**14 Number of Comments2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gale, Tony	(303) 886-8733	tony@kt-res.com	
Baumgras, Dan	(307) 321-3299	Dan@KT-Res.com	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Adams, Karen	(303) 886-8733	adams@kt-res.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261839	WELL	PR	11/01/2023	GW	103-10212	ANT HILL UNIT 18-42	PR

**General Comment:****ECMC Inspection Report Summary**

On Wednesday, 01/31/2024, Inspector Kirby Burchett, conducted a follow up field inspection at KT Resources LLC on the Ant Hill Unit 18-42 well, Location #316308, in Rio Blanco County, Colorado.

This location is within or in close proximity to Parks and Wildlife (CPW) District with Black Bear, High Priority, NSO, Density, and Other Consultation Habitats.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Insp. #702501296 on 5/10/23. Original due dates remain on unresolved Corrective Actions:

1. Random debris. (Unresolved)
2. Chemical containment open to wildlife. (Resolved)
3. Gas meter calibration not visibly displayed. (Resolved)
4. Stormwater BMPs need implementation and maintenance. (Unresolved)

While there during normal operations the following compliance issue was observed:

1. Gas meter calibration overdue.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	As Wellhead signs are replaced: The Well name; The API Number; and Its legal location, including the quarter/quarter section will be required.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	As Location Entrance signs are replaced: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available) will be required.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: (800) 288-0560 or 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Random debris on pumping unit and engine		
Corrective Action:	All trash, rubbish, and other waste material will be properly contained until removed from the Oil and Gas Location. At no time will trash, debris, or rubbish be placed or remain on the ground.	Date:	05/17/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	Livestock wire		
Corrective Action:		Date:	
Type	WELLHEAD		

Comment: <a href="#">Fence panels</a>					
Corrective Action:				Date:	

  

<b><u>Equipment:</u></b>						corrective date	
Type: Pump Jack		# 1					
Comment:							
Corrective Action:						Date:	
Type: Bradenhead		# 1					
Comment:							
Corrective Action:						Date:	
Type: Ancillary equipment		# 1					
Comment: <a href="#">Lube tank in containment</a>							
Corrective Action:						Date:	
Type: Horizontal Heater Treater		# 1					
Comment:							
Corrective Action:						Date:	
Type: Ancillary equipment		# 2					
Comment: <a href="#">Chemical tanks on containment</a>							
Corrective Action:						Date:	
Type: Deadman # & Marked		# 4					
Comment:							
Corrective Action:						Date:	
Type: Gas Meter Run		# 1					
Comment: <a href="#">Gas meter calibration out of compliance.</a>							
Corrective Action: <a href="#">Meters will be calibrated annually unless more frequent calibration is required by contractual obligations or by the Director.</a>						Date: <u>02/11/2024</u>	
Type: Bird Protectors		# 3					
Comment:							
Corrective Action:						Date:	

  

<b><u>Tanks and Berms:</u></b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:				Date:	

  

<b><u>Paint</u></b>	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

  

<b><u>Berms</u></b>	
---------------------	--

Inspector Name: Burchett, Kirby

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Other	Adequate				
Comment:	Metal and earth. Unlined				
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Other	Adequate				
Comment:	Metal and earth. Unlined				
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	261839	Type:	WELL	API Number:	103-10212	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	November 2023 Production Report								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Limited Stormwater inspection due to snow.  
  
Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403673252	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6414558">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6414558</a>
702502330	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6414553">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6414553</a>