

Inspection Photos

Location Name: CAERUS PICEANCE LLC, UNOCAL-66S96W/16LOT 13

Location ID: 335206

Date: 2/5/2024



Location Entrance – Photo #09093



Wellheads – Photo #09100

Inspection Photos

Location Name: CAERUS PICEANCE LLC, UNOCAL-66S96W/16LOT 13

Location ID: 335206

Date: 2/5/2024



Wellheads – Photo #09101



Separators – Photo #09097

Inspection Photos

Location Name: CAERUS PICEANCE LLC, UNOCAL-66S96W/16LOT 13

Location ID: 335206

Date: 2/5/2024



Tank Battery/No Battery Sign – Photo #09094



Debris Near Separators – Photo #09099

Inspection Photos

Location Name: CAERUS PICEANCE LLC, UNOCAL-66S96W/16LOT 13

Location ID: 335206

Date: 2/5/2024



Lack of Stabilization – Photo #09102



Lack of Stabilization – Photo #09104

Inspection Photos

Location Name: CAERUS PICEANCE LLC, UNOCAL-66S96W/16LOT 13

Location ID: 335206

Date: 2/5/2024



Lack of Stabilization – Photo #09105



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #09106**