

Inspection Photos

Location Name: CAERUS PICEANCE LLC, UNCOAL-ENCANA-66S96W/17NESE

Location ID: 335684

Date: 2/5/2024



Location Entrance – Photo #09108



Wellheads – Photo #09115

Inspection Photos


Location Name: CAERUS PICEANCE LLC, UNCOAL-ENCANA-66S96W/17NESE

Location ID: 335684

Date: 2/5/2024



Separators – Photo #09114



Tank Battery – Photo #09109

Inspection Photos

Location Name: CAERUS PICEANCE LLC, UNCOAL-ENCANA-66S96W/17NESE

Location ID: 335684

Date: 2/5/2024



Pig Station – Photo #09113



Stored Equipment – Photo #09111

Inspection Photos

Location Name: CAERUS PICEANCE LLC, UNCOAL-ENCANA-66S96W/17NESE

Location ID: 335684

Date: 2/5/2024



Debris – Photo #09112



Lack of Stabilization – Photo #09117

Inspection Photos

Location Name: CAERUS PICEANCE LLC, UNCOAL-ENCANA-66S96W/17NESE

Location ID: 335684

Date: 2/5/2024



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #09118**



Lease Road Lacks Stabilization – Photo #09119