

Storm Water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SHIDELER 19-8 (H19) Pad
Location ID: 334886



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas. Drainage
contributes to Middle Mamm Creek.
Section/Township/Range: 19 7S92W**



Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SHIDELER 19-8 (H19) Pad
Location ID: 334886



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.



Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SHIDELER 19-8 (H19) Pad
Location ID: 334886



Photo # 5901 Lack of stabilization/compaction/insufficient tracking BMP's



Photo # 5902 Lack of stabilization/compaction/insufficient tracking BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SHIDELER 19-8 (H19) Pad
Location ID: 334886



Photo # 5903 Lack of stabilization/compaction/insufficient tracking BMP's



Photo # 5904 Lack of stabilization/compaction/insufficient tracking BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SHIDELER 19-8 (H19) Pad
Location ID: 334886



Feb 7, 2024 at 11:31:36 AM

Photo # 5905 Lack of stabilization/compaction/insufficient tracking BMP's



Feb 7, 2024 at 11:32:05 AM

Photo # 5906 Lack of stabilization/compaction/insufficient tracking BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SHIDELER 19-8 (H19) Pad
Location ID: 334886



Photo # 5907 Lack of stabilization/compaction/insufficient tracking BMP's



Photo # 5908 Lack of stabilization/compaction/insufficient tracking BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC SHIDELER 19-8 (H19) Pad
Location ID: 334886



Photo # 5909 Lack of stabilization/compaction/insufficient tracking BMP's



Photo # 5910 Lack of stabilization/compaction/insufficient tracking BMP's