

# Inspection Photos

Loc: 321575

Operator: MULL DRILLING COMPANY INC

Inspection Date: 2/7/2024

County: CHEYENNE



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing north toward wellsite location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:321575 | Date: 2/7/2024



## Inspection Photos



**Photo 2.** There is weed debris around the equipment that needs to be removed.





## Inspection Photos



**Photo 3.** There is oily fluids inside the secondary containment of the barrels.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:321575 | Date: 2/7/2024



## Inspection Photos



**Photo 4.** There is oily fluids inside the secondary containment of this white tank. There is oil staining on the ground and the lid is not secured.

