

Inspection Photos

Loc: 321574

Operator: MULL DRILLING COMPANY INC

Inspection Date: 2/7/2024

County: CHEYENNE



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south toward wellsite location.



Inspection Photos



Photo 2. Facing toward the wellhead. There are stained soils at wellhead that should be cleaned up.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:321574 | Date: 2/7/2024

Inspection Photos



Photo 3. Facing northwest. There is an open excavation along the pipeline. This area should be marked with cones or safety fence to prevent accidental entry. .



Inspection Photos



Photo 4. Facing toward the equipment at the south side of the location..



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321574 | Date: 2/7/2024

Inspection Photos



Photo 5. The open top tank is adequately netted. There was a spilled that occurred and oily soils need to be cleaned up.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:321574 | Date: 2/7/2024

Inspection Photos



Photo 6. Facing east toward the backside of the open top tank. It appears some staining is along the outside of the berm.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:321574 | Date: 2/7/2024

Inspection Photos



Photo 7. Facing toward the backside of the open top tank. Stained soils will need to be cleaned up..



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321574 | Date: 2/7/2024