

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/07/2024

Submitted Date:

02/08/2024

Document Number:

713600712

**FIELD INSPECTION FORM**

Loc ID 321574 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 61250  
Name of Operator: MULL DRILLING COMPANY INC  
Address: 1700 N WATERFRONT PKWY B#1200  
City: WICHITA State: KS Zip: 67206-

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name   | Phone          | Email                       | Comment |
|----------------|----------------|-----------------------------|---------|
| OBryhim, Reesa |                | robryhim@mulldrilling.com A |         |
| Mull, Jennifer | (316) 264-6366 | jmull@mulldrilling.com      |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 207334      | WELL | PR     | 03/01/2021  | OW         | 017-06269 | MULL UNIT 18  | RI          |

**General Comment:**

[This is a location and stormwater management inspection.](#)  
[See attached photos and additional details within this report.](#)

**Location**

|                    |        |  |       |
|--------------------|--------|--|-------|
| <b>Lease Road:</b> |        |  |       |
| Type               | Access |  |       |
| comment:           |        |  |       |
| Corrective Action  |        |  | Date: |

Overall Good:

|                      |   |  |                  |
|----------------------|---|--|------------------|
| <b>Signs/Marker:</b> |   |  |                  |
| Type                 | OTHER   |  |                  |
| Comment:             | There is an open excavation that is not clearly marked to prevent accidental entry. |  |                  |
| Corrective Action:   | Comply with Rule 210.   |  | Date: 02/10/2024 |

|                                  |   |  |             |
|----------------------------------|---|--|-------------|
| <b>Emergency Contact Number:</b> |   |  |             |
| Comment:                         | <input style="width: 100%;" type="text"/> |  |             |
| Corrective Action:               | <input style="width: 100%;" type="text"/> |  | Date: _____ |

Overall Good:

|                    |   |        |                  |
|--------------------|---|--------|------------------|
| <b>Spills:</b>     |   |        |                  |
| Type               | Area  | Volume |                  |
| Crude Oil          | Tank  |        |                  |
| Comment:           | There was a spill at the open top tank that needs to be cleaned up. There are also stained soils at the wellhead. |        |                  |
| Corrective Action: | Control and contain spills/releases and clean up per Rule 912.a.  |        | Date: 03/08/2024 |

|  |   |
|--|---|
| In Containment: No                                     |   |
| Comment:   | <input style="width: 100%;" type="text"/> |
| <input type="checkbox"/> Multiple Spills and Releases? |   |

|                    |                     |  |       |
|--------------------|---------------------|--|-------|
| <b>Fencing/:</b>   |                     |  |       |
| Type               | LOCATION            |  |       |
| Comment:           | Location is fenced. |  |       |
| Corrective Action: |                     |  | Date: |

|                    |   |  |       |
|--------------------|---|--|-------|
| <b>Venting:</b>    |   |  |       |
| Yes/No             |   |  |       |
| Comment:           | <input style="width: 100%;" type="text"/> |  |       |
| Corrective Action: |   |  | Date: |

|                    |   |  |       |
|--------------------|---|--|-------|
| <b>Flaring:</b>    |   |  |       |
| Type               |   |  |       |
| Comment:           | <input style="width: 100%;" type="text"/> |  |       |
| Corrective Action: |   |  | Date: |

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 713600713    | Inspection photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6422749">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6422749</a> |