

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/08/2024

Submitted Date:

02/08/2024

Document Number:

690012272

FIELD INSPECTION FORM

Loc ID 336317 Inspector Name: Carlile, Craig On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------|---------------------------------|
| , Oxy | | ECMCInspections@Oxy.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 271498 | WELL | SI | 07/01/2020 | OW | 123-22074 | BARCLAY 4-27 | TA |
| 287865 | WELL | SI | 07/01/2020 | GW | 123-24430 | BARCLAY 29-22 | TA |

General Comment:

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|----------------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | OOSLAT tags at both wells. | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | |
|--------------------|----------------------|----------------------------|
| Comment: | <input type="text"/> | |
| Corrective Action: | <input type="text"/> | Date: <input type="text"/> |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Pipe panel | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|--------------------|-----|-------|-----------------|
| Type: Plunger Lift | # 0 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---------------------------------|----------|---------------------|---------|-----------------------|
| | | | CENTRALIZED BATTERY | | 40.199670,-104.769950 |
| Comment: | Battery location number: 326783 | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | |
|------------------|----------------------|
| Condition | <input type="text"/> |
| Other (Content) | <input type="text"/> |
| Other (Capacity) | <input type="text"/> |
| Other (Type) | <input type="text"/> |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
| | | | | |

| | | |
|--------------------|--|-------|
| Comment: | | |
| Corrective Action: | | Date: |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| |
|--|
| |
|--|

Inspected Facilities

Facility ID: 271498 Type: WELL API Number: 123-22074 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well not connected with flow line.
OOSLSAT tags Applied

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 05/08/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: None
End Surf Csg Pressure: --

Comment: Plumbed to surface.

Corrective Action: _____ Date: _____

Facility ID: 287865 Type: WELL API Number: 123-24430 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Wellhead not connected with flow line.
OOSLAT tags applied.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 05/16/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 15 Fluid Type: None
End Surf Csg Pressure: --

Comment: Plumbed to surface.

Corrective Action: _____ Date: _____

COGCC Comments

| Comment | User | Date |
|-------------------------------------|----------|------------|
| <u>Routine wellhead inspection.</u> | carlilec | 02/08/2024 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 690012273 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6422815 |