

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/07/2024

Submitted Date:

02/08/2024

Document Number:

707602358

**FIELD INSPECTION FORM**

Loc ID 413386 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 2001 16TH STREET SUITE 900  
City: DENVER State: CO Zip: 80202

**Findings:**

- 10 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
413385	WELL	TA	06/01/2021	GW	123-30694	THISTLE DOWN B 31-17	TA

**General Comment:**

This is a WELL inspection.  
Well(s): 1: Temporarily Abandoned | TA.  
Battery: Inactive | Shut-down.

Centralized Battery serves 1 Location ID (413386).  
(Well(s): 1: Temporarily Abandoned | TA).

Centralized Battery Formerly served 1 Location ID (327042).  
(Well(s): 1: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID (Pending).

Reference (Associated Well(s), Battery Inspections):  
A.) Field Inspection Report doc. #707602358 and/or Location ID #413386 for TA Well(s) info.  
B.) Field Inspection Report doc. #707602360 and/or Location ID #327042 for PA Well(s) info.  
C.) Field Inspection Report doc. #707602362 and/or Location ID #413386 for Battery / Facility, Equipment info.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Overgrown vegetation at wellsite. Refer to Rule 606.c for guidance.		
Corrective Action:	*Remove, manage, & control overgrown vegetation around wellsite. Comply with Rule 606.c. Corrective Action date: 03/11/2024. (30-days). See photo #1. *Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.		Date: <u>03/11/2024</u>

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:

<b>Equipment:</b>				corrective date
Type: Other	# 1			
Comment:	Wellhead: w/ Master & casing valves.			
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:	Appears plumbed to surface.			
Corrective Action:				Date:

<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.355719,-104.584638

Comment:	Centralized Battery serves 1 Location ID (413386). (Well(s): 1: Temporarily Abandoned   TA).  Centralized Battery serves 1 Tank Battery Facility ID (Pending).	
Corrective Action:		Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 413385 Type: WELL API Number: 123-30694 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.  
Disconnected from flowline.  
Locked-Out, Tagged-Out | LOTO.  
OOSLAT applied at separator.  
Blue TA tag posted.  
CECMC records last production: 08/2016.  
  
Form 4 on file. TA date: 04/15/2019. Approved.  
DH-CIBP set.  
Form 6A on file. Out-of-Svc Designation.  
Date: 08/01/2016. Approved.

Corrective Action:

Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 08/29/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

Reclamation - Storm Water - Pit						
<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p><b>CECMC Inspection Report Summary:</b></p> <p>On WED 02/07/2024 at approximately 12:15 hrs. I, Bret Evins, conducted an onsite inspection at:                      Operator Name: NOBLE ENERGY INC                      Location Name: THISTLE DOWN B/31-17                      Location ID: 413386                      Well Name(s):                      Thistle Down B 31-17.                      API:                      123-30694.                      Location County: Weld County, Colorado                      Weather: Mostly Cloudy, damp from prior storm.</p> <p>While there, I observed:                      Well(s): 1: Temporarily Abandoned   TA.                      Battery: Inactive   Shut-down.</p> <p>During this inspection the following possible compliance issue(s) were observed:                      1.) Overgrown vegetation at wellsite.                      Refer to Rule 606.c for guidance.                      *Remove, manage, &amp; control overgrown vegetation around wellsite.                      Comply with Rule 606.c.                      Corrective Action date: 03/11/2024. (30-days).                      See photo #1.</p> <p>*Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.</p> <p>*A follow up on this site inspection will be conducted to ensure that compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	02/08/2024

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602359	Site photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6423168">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6423168</a>