

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/08/2024

Submitted Date:

02/08/2024

Document Number:

697008896

FIELD INSPECTION FORMLoc ID 327941 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|---|---------|
| , | | rbucogccinspectionreports@c hevron.onmicrosoft.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 247548 | WELL | TA | 05/03/2023 | GW | 123-15345 | JEPSEN 13-15 F | TA |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|--|-------|------------|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Crude oil tanks contents/capacity decals require replacement. see attached photos. | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | Date: | 03/08/2024 |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|----------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Panel | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Gas Meter Run | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Pig Station | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Automation array | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 3 | | |

| | | | |
|-------------------------------|--|-------|--|
| Comment: | | Date: | |
| Corrective Action: | | Date: | |
| Type: Flow Line | # 1 | | |
| Comment: | OOSLAT | Date: | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | Bradenhead valve is exposed at surface | Date: | |
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 1 | | |
| Comment: | | Date: | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CRUDE OIL | 2 | 300 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---------|----------|-------------|---------|--------|
| PRODUCED WATER | 2 | <50 BBLS | BV CONCRETE | | , |
| Comment: | 48 bbls | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Inspected Facilities | | | | | | | | | |
|---|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 247548 | Type: | WELL | API Number: | 123-15345 | Status: | TA | Insp. Status: | TA |
| Idle Well | | | | | | | | | |
| Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned | | | | | | | | | |
| Reminder: | | | | | | | | | |
| Comment: Form 6A #403118488 | | | | | | | | | |
| Corrective Action: | | | | | | | | | |
| Date: | | | | | | | | | |
| BradenHead | | | | | | | | | |
| Date of Last Brhd Test: 05/29/2023 | | | | | | | | | |
| Annual Brhd Completed? Yes | | | | | | | | | |
| Last Brhd Test Results | | | | | | | | | |
| Initial Surf Csg Pressure: 0 | | | | | | | | | |
| Fluid Type: | | | | | | | | | |
| End Surf Csg Pressure: 0 | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | | | | | | |
| Date: | | | | | | | | | |

Reclamation - Storm Water - Pit

Storm Water:

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Gravel | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|--|-----------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Thursday 2/8/2024 at approximately 11:45 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the Noble Energy Jepsen 13-15F location #327941 in Weld County, Colorado.</p> <p>While there, I observed that the crude oil tanks contents/capacity placards required replacement. During this inspection the following possible compliance issues were observed: Rule 605.h. with a corrective action date of 3/8/2024.</p> <p>A follow up inspection on this site needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of the inspection report.</p> | petersont | 02/08/2024 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 697008897 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6423260 |