

Inspection Photos
Location Name: CAERUS PICEANCE LLC O19E Pad
Location #: 334790



Photo # 5959 From entrance to location



Photo # 5960 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC O19E Pad
Location #: 334790



Photo # 5961 Debris



Photo # 5962 Wellheads lack required signage/signs missing required information

Inspection Photos
Location Name: CAERUS PICEANCE LLC O19E Pad
Location #: 334790



Photo # 5963 Wellheads lack required signage/signs missing required information



Photo # 5964 Wellheads lack required signage/signs missing required information