

Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/8SESE

Location ID: 335634

Date: 2/8/2024



Wellheads – Photo #09185



Separators – Photo #09189

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/8SESE

Location ID: 335634

Date: 2/8/2024



Tank Battery – Photo #09190



Lack of Stabilization – Photo #09187

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/8SESE

Location ID: 335634

Date: 2/8/2024



Lack of Stabilization – Photo #09188



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #09194**