

KP Kauffman - COGCC Inspection Photos
Location: Johnson #1 Flowline Release
Spill ID #485936 Date 02/09/2024



Signage at Johnson #1 Well



View south from Johnson #1 wellhead to fenced excavation area where release occurred. Well is (SI); No OOSLAT in place at wellhead.

KP Kauffman - COGCC Inspection Photos
Location: Johnson #1 Flowline Release
Spill ID #485936 Date 02/09/2024



View of on location flowline pipe exposed in excavation; replacement section of 3" OD fiberglass pipe in area of failure.



View of transitional fittings used to connect 3" OD fiberglass pipe to existing 2" carbon steel flowline pipe at south wall of excavation. Threaded fitting connections and a bolted clamp are being used; external pipe coating appears to be inadequate to protect from external and/ or thread corrosion.

KP Kauffman - COGCC Inspection Photos
Location: Johnson #1 Flowline Release
Spill ID #485936 Date 02/09/2024



View of flowline pipe exposed in excavation; replacement section of fiberglass pipe is submerged under water/ fluids.



View of soils stockpile and fenced excavation/ work areas on location.