

Inspection Photos
Location Name: Lansons Farm 6
Location ID: 317931



Photo 1 Location.

Photo 2 Wellsite.

Inspection Photos
Location Name: Lansons Farm 6
Location ID: 317931



Energy & Carbon Management Commission
40.08937, -104.96871, 4914.1ft, 88°
02/12/2024 14:05:16



Energy & Carbon Management Commission
40.08944, -104.96869, 4926.5ft, 359°
02/12/2024 14:05:38

Photo 3 WH sign is faded.

Photo 4 WH.

Inspection Photos
Location Name: Lansons Farm 6
Location ID: 317931



Photo 5 Prime Mover/Electric motor and electric panel.

Photo 6 Electric panel, meter box and transformers.

Inspection Photos
Location Name: Lansons Farm 6
Location ID: 317931



Photo 7 Gear box on the pump jack is leaking oil onto the ground.



Photo 8 Gear box on the pump jack is leaking oil onto the ground..

Inspection Photos
Location Name: Lansons Farm 6
Location ID: 317931



Photo 9 Gear box on the pump jack is leaking oil onto the ground.

Photo 10 Gear box on the pump jack is leaking oil onto the ground.