

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/12/2024

Submitted Date:

02/12/2024

Document Number:

702403091**FIELD INSPECTION FORM**Loc ID 311286 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

10 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	All Inspections
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240096	WELL	PR	07/01/2017	OW	123-07884	LANSONS FARMS 1	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Good Housekeeping:		
Type	UNUSED EQUIPMENT	
Comment:	Unused Ancillary equipment(Electric panel, meter box and transformers)	
Corrective Action:	Comply with Rule 606	Date: 03/13/2024

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:		
Type	PUMP JACK	
Comment:	Fabricated steel pipe	
Corrective Action:		Date:
Type	OTHER	
Comment:	Unused ancillary equip. has fabricated steel pipe and round stock.	
Corrective Action:		Date:

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	electric panel, meter box and transformers all are unused.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas engine		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

<u>Venting:</u>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	240096	Type:	WELL	API Number:	123-07884	Status:	PR	Insp. Status:	SI
Producing Well									
Comment:	PR								
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	02/20/2023		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	0	Fluid Type:						
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary On Monday 2-12-2024 at approximately 1220 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Operator: KP Kauffman Location name: Location ID # 311286 Well Name: Lansons Farm 1 API # 05-123-07884 County: Weld Weather: Clear Location: Wet, Muddy with some snow. While there, I observed a wellsite, SI at the time of the inspection. During this inspection, I observed the following possible compliance issue: 606 Housekeeping: Unused equipment, CA date 3-13-2024 See attached photos. A follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.</p>	revasr	02/12/2024

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702403092	location photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6427026