

Inspection Photos
Location Name: S&B 5-11 HZ Pad
Location ID: 474765



Lease road entrance



Energy & Carbon Management Commission
40.32935, -104.97546, 1499.1m, 261°
02/13/2024 09:17:56

Production facility

Inspection Photos
Location Name: S&B 5-11 HZ Pad
Location ID: 474765



Energy & Carbon Management Commission
40.3299, -104.97726, 1501.2m, 183°
02/13/2024 09:12:50

Wellheads



Energy & Carbon Management Commission
40.32923, -104.97557, 1499.6m, 204°
02/13/2024 09:39:26

Lease road damage

Inspection Photos
Location Name: S&B 5-11 HZ Pad
Location ID: 474765



West side of pad damage



East side of pad damage