

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/13/2024

Submitted Date:

02/14/2024

Document Number:

709700363

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
 320118 _____ Huck, Keith _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10651
 Name of Operator: VERDAD RESOURCES LLC
 Address: 1125 17TH STREET SUITE 550
 City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments
 0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|--------------------------|-----------------|
| , | | Regulatory@verdadoil.com | All inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 202713 | WELL | PR | 01/01/2015 | GW | 001-08118 | GRAND 1 | PR |

General Comment:

Location

Overall Good:

| Signs/Marker: | | | |
|----------------------|----------------------|-------|--|
| Type | BATTERY | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

| | | | |
|----------------------------------|----------|--|-------------|
| Emergency Contact Number: | | | |
| Comment: | Adequate | | Date: _____ |
| Corrective Action: | | | |

Overall Good:

| Spills: | | | |
|----------------|------|--------|--|
| Type | Area | Volume | |
| | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

| Fencing/: | | | |
|--------------------|----------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Pipe | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | Pipe | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | 4 Strand Barbed Wire | | |
| Corrective Action: | | Date: | |

| Equipment: | | | corrective date |
|-----------------------------------|-----|-------|-----------------|
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |

| | | | | |
|---------------------|----------------------------------|--|-------|--|
| Comment: | Appears to be plumbed to surface | | Date: | |
| Corrective Action: | | | Date: | |
| Type: Gas Meter Run | # 1 | | | |
| Comment: | | | Date: | |
| Corrective Action: | | | Date: | |
| Type: Plunger Lift | # 1 | | | |
| Comment: | | | Date: | |
| Corrective Action: | | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 1 | 300 BBLS | STEEL AST | | 39.968065,-104.653557 |
| Comment: | | | | | Date: |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficent | Base Sufficent | Adequate |
| Comment: | | | | Date: |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|----------|---------|--------|
| PRODUCED WATER | 1 | 100 BBLS | Open Top | | |
| Comment: | | | | | Date: |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------------------------------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficent | Base Sufficent | Adequate |
| Comment: | Shares berm with production tank | | | Date: |
| Corrective Action: | | | | Date: |

AirsID

| | |
|------------|--------|
| API Number | AirsID |
|------------|--------|

Wells Served By Facilities Above

API Number

001-08118

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 202713 Type: WELL API Number: 001-08118 Status: PR Insp. Status: PR

Producing Well

Comment: [PR](#)

Corrective Action:

Date:

COGCC Comments

| Comment | User | Date |
|------------------------------------|-------|------------|
| Routine Inspection | huckk | 02/14/2024 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 709700364 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6429316 |