

# Inspection Photos

Loc: 414696

Operator: KTM OPERATING LLC

Inspection Date: 2/13/2024

County: LINCOLN



## Inspection Photos



**Photo 1.** Facing north along the main road. There is erosion along the road sides and there are no BMP's installed to prevent further rerosion.



Inspection Photos



**Photo 2.** Facing west along the access road. There is erosion along the road from stormwater directed down the slope of the road.



Inspection Photos



**Photo 3.** Facing north toward the wellsite location.



## Inspection Photos



**Photo 4.** Facing toward the wellhed. There is oil stained soils at the wellhead that need to be cleaned up. There is inadequate signage at the well.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:414696 | Date: 2/13/2024

## Inspection Photos



**Photo 5.** There are two 5 gallon containers one of which is full of oily liquid that has spilled onto the ground. There are undesirable weed debris around the equipment which is a fire hazard.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:414696 | Date: 2/13/2024

Inspection Photos



**Photo 6.** There is some pipe and an empty chemical container that needs to be removed..



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:414696 | Date: 2/13/2024