

Final Reclamation Inspection

February 13th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333468

Inspection Document #: 714000412

La Plata County, CO

Township: SWSW 14 34N 8W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Mayfield 14U-01 2, 4
Location ID: 333468



Photo 1. View of the disturbance from the entrance facing center.



API #: 067-09031, 09435



Inspection Photos
Location Name: Mayfield 14U-01 2, 4
Location ID: 333468



2/13/24
+37.186615,-107.691297
359° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of the eastern interim reclamation area facing north. Comprised of smooth brome and crested wheatgrass.

API #: 067-09031, 09435

Inspection Photos
Location Name: Mayfield 14U-01 2, 4
Location ID: 333468



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Oily bucket CA identified in the previous inspection doc #712700605 has been addressed/resolved.

API #: 067-09031, 09435

Inspection Photos
Location Name: Mayfield 14U-01 2, 4
Location ID: 333468



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Reference area comprised of smooth brome and juniper.

API #: 067-09031, 09435