

# Final Reclamation Inspection

February 13th, 2024

Operator: Simcoe LLC - 10749

Location ID: 312017

Inspection Document #: 714000414

La Plata County, CO

Township: SENE 31 34N 7W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
 Location Name: Fairfield Farms 2, 4  
 Location ID: 312017



Photo 1. View of the disturbance from the entrance facing center.



Inspection Photos  
Location Name: Fairfield Farms 2, 4  
Location ID: 312017



**Photo 2.** Cut and fill slopes lacking vegetation with exposed soil. Disturbance has been degraded by exposure to cattle in the area, no vegetation establishment in the interim reclamation areas.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-09065, 09090

Inspection Photos  
Location Name: Fairfield Farms 2, 4  
Location ID: 312017

2/13/24  
+37.150063, -107.643547  
136° SE



**Photo 3.** View of deteriorating produced water sign that is no longer displaying max capacity.

Inspection Photos  
Location Name: Fairfield Farms 2, 4  
Location ID: 312017



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** View of unused oil and gas fence equipment stored on location.

API #: 067-09065, 09090

Inspection Photos  
Location Name: Fairfield Farms 2, 4  
Location ID: 312017



Inspection Photos  
Location Name: Fairfield Farms 2, 4  
Location ID: 312017


2/13/24  
+37.150557,-107.643779  
339° N



**Photo 6.** Northwest corner of the disturbance does not appear needed for production operations and remain un-reclaimed.



Inspection Photos  
Location Name: Fairfield Farms 2, 4  
Location ID: 312017



**Photo 7.** Polygon represents approximate areas of the location not reasonably needed for production