

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 34-12 (N34) Pad

Location #: 334661



Photo # 6469 From entrance to location



Photo # 6470 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 34-12 (N34) Pad

Location #: 334661



Photo # 6471 Location



Photo # 6472 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 34-12 (N34) Pad

Location #: 334661



Feb 13, 2024 at 10:43:57 AM
CO

Photo # 6473 Location



Feb 13, 2024 at 10:51:00 AM
CO

Photo # 6474 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 34-12 (N34) Pad

Location #: 334661




Photo # 6475 Hole in liner/liner needs maintenance



Photo # 6476 Rupture disc vent line lacks cap

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 34-12 (N34) Pad

Location #: 334661




Photo # 6477 Rupture disc vent line lacks cap