

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/05/2024

Submitted Date:

02/08/2024

Document Number:

707800702**FIELD INSPECTION FORM**Loc ID 335674 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments

4 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	
Smelser, Wayne		wayne.smelser@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
360	WELL	PR	09/20/2008	GW	045-15486	N. PARACHUTE EF12B-DX D31 59	PR
362	WELL	PR	09/21/2008	GW	045-15487	N. PARACHUTE EF11C D31 595	PR
292255	WELL	PR	09/17/2008	GW	045-14664	N. PARACHUTE EF 12A D31 595	PR
292256	WELL	PR	06/01/2018	GW	045-14663	N. PARACHUTE EF11D D31 595	PR
292258	WELL	PR	09/17/2008	GW	045-14665	N.PARACHUTE EF14B D31 595	PR
292259	WELL	PR	09/17/2008	GW	045-14661	N. PARACHUTE EF14A D31 595	PR
292260	WELL	PR	09/18/2008	GW	045-14660	N. PARACHUTE EF12D D31	PR
292261	WELL	PR	09/18/2008	GW	045-14659	N. PARACHUTE EF12C D31 595	PR

General Comment:

ECMC Inspection Report Summary

On Monday 2/5/2024, I, Inspector Scott Ramsey, conducted a follow up inspection at Caerus N. Parachute D31 595, at Location # 335674 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

C/A from inspection from document # 708902599 (Open cellars) have been filled some with dirt but are still open.

During this inspection the following compliance issues were observed:

1. Cellars are still open (small wildlife could potentially get trapped in cellars)
2. Well heads are lacking information.
3. Random debris,
4. Location /access road are lacking stabilization and tracking BMP's.

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

LocationOverall Good: ☐

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Well heads are lacking information.		
Corrective Action:	Provide proper signage	Date:	03/21/2024

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris	Date:	02/16/2024
Type	OTHER		
Comment:	Cellars are still open (small wildlife could potentially get trapped in cellars)		
Corrective Action:	Operators are responsible for ensuring that operations are conducted with due regard for the safety of employees, for the preservation and conservation of property, and for protecting and minimizing adverse impacts to public health, safety, welfare, the environment, and wildlife resources. Install means of egress or eliminate wildlife access	Date:	02/16/2024

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 12		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks in plastic containments		
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 8		
Comment:			

Corrective Action:		Date:	
<u>Venting:</u>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities						
Facility ID:	360	Type:	WELL	API Number: 045-15486	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	362	Type:	WELL	API Number: 045-15487	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	292255	Type:	WELL	API Number: 045-14664	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	292256	Type:	WELL	API Number: 045-14663	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	292258	Type:	WELL	API Number: 045-14665	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	292259	Type:	WELL	API Number: 045-14661	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	292260	Type:	WELL	API Number: 045-14660	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	292261	Type:	WELL	API Number: 045-14659	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing					
Corrective Action:						Date:

--

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps						
		Compaction	Fail			
Ditches						
Compaction	Fail					
		Tracking Pad	Fail			No signs of a tracking BMP
Rip Rap						
Berms						

Comment: 1. Location /access road are lacking stabilization and tracking BMP's.

Corrective Action: Install, maintain or repair required BMPs and eliminate tracking issues.

Date: 03/21/2024

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403681438	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6423177
707800706	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6423171