

# Final Reclamation Inspection

February 13th, 2024

Operator: Simcoe LLC - 10749

Location ID: 306883

Inspection Document #: 714000429

La Plata County, CO

Township: SENE 14 34N 8W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Dickens 44-14 2  
Location ID: 306883

2/13/24  
+37.194139,-107.681156  
298° NW



Photo 1. View of the disturbance from the entrance facing center.




Inspection Photos  
Location Name: Dickens 44-14 2  
Location ID: 306883



**Photo 2.** Unused tubing CA identified in previous inspection doc #702500200 has been addressed/resolved.

Inspection Photos  
Location Name: Dickens 44-14 2  
Location ID: 306883



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** Stormwater CA identified in previous inspection doc #702500200 has been addressed/resolved.

API #: 067-08959

Inspection Photos  
Location Name: Dickens 44-14 2  
Location ID: 306883



**Photo 4.** Impacted surface material remains at well head.



Inspection Photos  
Location Name: Dickens 44-14 2  
Location ID: 306883



**Photo 5.** Musk thistle observed in the eastern interim reclamation area.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-08959

Inspection Photos  
Location Name: Dickens 44-14 2  
Location ID: 306883

2/13/24  
+37.194232,-107.681251  
78° E



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 6.** Reference area comprised of juniper and smooth brome.

API #: 067-08959