

Interim Reclamation and Stormwater Inspection

Date: 2/9/24

Operator: Smith Energy LLC - 10536

Location ID: 317216

Inspection Document #: 713900359

Washington County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: Small, R.-62S50W 35NWSW

Location ID: 317216



Photo 1. The photo was taken from the well location facing North. The photo illustrates the operator sign with covered emergency contact information.



Photo 2. The photo was taken from the well location facing Northwest. The photo illustrates the tank placard is faded and illegible and the secondary containment is full and unprotected without wildlife netting.

Inspection Photos

Location Name: Small, R.-62S50W 35NWSW

Location ID: 317216



Photo 3. The photo was taken from the well location facing Northwest. The photo illustrates the active skim pit on location with the damaged tinhorn.




Photo 4. The photo is imagery from the ECMC database and illustrates the three unregistered active pits at the well location.

Inspection Photos

Location Name: Small, R.-62S50W 35NWSW

Location ID: 317216



Photo 5. The photo was taken from the well location facing Southeast. The photo illustrates the access road.



Photo 6. The photo was taken from the well location facing East. Refer to the comment for photo 5.

Inspection Photos

Location Name: Small, R.-62S50W 35NWSW

Location ID: 317216



Photo 7. The photo was taken from the well location facing Northwest. The photo illustrates oil and gas equipment; meter sheds and what appears to be midstream equipment.



Photo 8. The photo was taken from the well location facing North. The photo illustrates the interim areas are adequately vegetated.

Inspection Photos

Location Name: Small, R.-62S50W 35NWSW

Location ID: 317216



Photo 9. The photo was taken from the well location facing West. The photo illustrates midstream equipment on the well location.



Photo 10. The photo was taken from the well location facing West. Refer to the comment for photo 9.

Inspection Photos
Location Name: Small, R.-62S50W 35NWSW
Location ID: 317216



Photo 11. The reference photo was taken from the North side of the well location facing North. The photo illustrates reference areas contain Sandhill sagebrush, Yucca, Sand dropseed, among other vegetation.