

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 21-10B (I21) Pad

Location #: 324196



Photo # 6523 From entrance to location



Photo # 6524 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 21-10B (I21) Pad

Location #: 324196



Photo # 6525 Location



Photo # 6526 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 21-10B (I21) Pad

Location #: 324196



Photo # 6527 Location



Photo # 6528 PRV vent line lacks cap

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 21-10B (I21) Pad

Location #: 324196




Photo # 6529 PRV vent line lacks cap

