

**Location ID: 335228**



### Location



## Battery signage

Caerus  
B36  
Location ID: 335228



Location



Location



Caerus  
B36  
Location ID: 335228



Location



Location



Caerus  
B36  
Location ID: 335228



Lack of stabilization/compaction and tracking BMP's



Lack of stabilization/compaction and tracking BMP's



Caerus  
B36  
Location ID: 335228



**Lack of stabilization/compaction and tracking BMP's**



**Lack of stabilization/compaction and tracking BMP's**



Caerus  
B36  
Location ID: 335228



Open pipe on glycol tank



Lack of stabilization/compaction and tracking BMP's



Caerus  
B36  
Location ID: 335228



Lack of stabilization/compaction and tracking BMP's



Lack of stabilization/compaction and tracking BMP's



Caerus  
B36  
Location ID: 335228



Debris



Lining in secondary containment has open holes