


Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/29NENE

Location ID: 335075

Date: 2/13/2024



Wellheads – Photo #09262



Separators – Photo #09267

Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/29NENE

Location ID: 335075

Date: 2/13/2024



Tank Battery – Photo #09264



Weathered Battery Sign – Photo #09265

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/29NENE

Location ID: 335075

Date: 2/13/2024



Open-Ended Load Line – Photo #09266



Lack of Stabilization – Photo #09268

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/29NENE

Location ID: 335075

Date: 2/13/2024



Lack of Stabilization on Lease Road – Photo #09269



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #09270