

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/17SENE

Location ID: 324184

Date: 2/13/2024



Wellheads – Photo #09291



Separators – Photo #09294

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/17SENE

Location ID: 324184

Date: 2/13/2024



Tank Battery – Photo #09297



Lack of Stabilization – Photo #09293

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/17SENE

Location ID: 324184

Date: 2/13/2024



Lack of Stabilization – Photo #09296



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #09298**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/17SENE

Location ID: 324184

Date: 2/13/2024



Insufficient Administrative Control – Photo #09300